

Photo 28. 4th floor, Room 414 (break room) - Location of dust sample #2 (top of wall mounted cabinets)




Photo 29. 3rd floor, outside room 311 - Impact damage at recessed light fixture




Photo 30. 3rd floor, west hall adjacent to lobby - Location of dust sample #3 -Top of emergency light




Photo 31. B Floor - east hallway - Close-up of damaged acoustical plaster in hallway




Photo 32. B Floor - Purchasing B7/B5 - View of acoustical plaster in storage room
(location of dust sample #4 – top of shelf)

ARKANSAS STATE HOSPITAL (ASH) – Hospital Administration,
Canteen, Nursing Administration and Admissions Buildings

Building Location: 4313 W Markham Street Little Rock, Arkansas

Date of Site Visit: 9/07/06

Field Notes, Background & General Observations

Building Type: Hospital Admin - 3-story mid rise office plus basement
Canteen, Nursing Admin & Admissions – 1-story buildings
Cast concrete structures

Material Type: Asbestos-Containing Acoustical Spray finish applied to
plaster ceilings that have been coated with a white latex-
based paint.

Acoustical Spray present is a vermiculite based material
with a taupe colored appearance – identified as a WR Grace
Zonolite product.

Material Analysis: Previous bulk sample analysis by EPA/600/R-93/116
indicates acoustical spray is asbestos containing

Material Location: Applied to most of the ceilings through out the four
buildings.

Accessibility: Open – direct access and fallout potential to all building
occupants

Most areas of the ceiling are beyond arm reach height of
occupants with out a ladder (limiting direct contact).

Material Friability: Moderately Friable with moderate to thick paint applied to
most surfaces.

Material Damage: Obvious minor delamination observed throughout
application (evidenced by acoustical spray dust and debris
deposited on horizontal surfaces below the ceiling
(including wall mounted cabinets, room dividers,
door/window frames and moldings) also evidence of
localized impact damage observed in a few isolated areas.

Based on walk-thru, some renovations and maintenance
work have taken place (potentially impacting the acoustical
spray ceiling). Building staff report some isolated areas of
previous acoustical spray abatement.

Current Material Condition: Fair Overall – acoustical spray generally appears to be substantially intact, however fine dust and debris are visible on many horizontal surfaces.

Physical Assessment: Moderately Friable

Damage Assessment: DAMAGED - Approximately 5 to 8% distributed damage with sporadic areas of localized damage (<25%)

Material Category: Damaged Friable Surfacing ACM

Potential for Disturbance: Moderate – in most areas the sprayed ceilings are not readily reachable to occupants other than maintenance staff, however, a few areas with lower ceiling heights exist which present a significantly higher potential for direct disturbance.

Freq. of Potential Contact: Moderate – in most building areas maintenance and building occupants are aware of asbestos sprayed ceilings in the building and know not to purposely disturb them.

Influence of Vibration: Low – in most areas.

Potential for Air Erosion: Moderate – supply and return air in the building is directed across the acoustical sprayed ceiling.

Overall Rating: Potential for Future Damage

Contamination Assessment

Dust Samples: Six micro-vacuum settled dust samples were collected and analyzed from horizontal surfaces situated directly beneath the acoustical spray. Observations (relative to morphology, matrix and color) made at the time of dust collection confirmed that the dust and debris collected in the samples were from delaminated/dislodged acoustical spray applied directly above the vacuumed surface. Analysis of the dust samples indicates extreme to slight contamination depending on the individual building, based on asbestos concentrations ranging from approximately 4.34 million to 2.65 billion asbestos fibers per square foot. Refer to table below: